



Model 2746_25_D




Examples


X=444, Y=158, Z=16, DH=4, H=4, PL=19, PSE=1, OL=5, OR=5, OT=10, OB=10, TX=0, TY=0, TS=1, TR=0, GE=0




PL=25, other parameters are the same



PL=25, TR=45, other parameters are the same



TX=-380, TY=-90, TS=2, PL=9, TR=45, other parameters are the same



Parameters

Main

Name	Code	Unit
Overall dimension X	X	mm
Overall dimension Y	Y	mm
Overall dimension Z	Z	mm
Pattern width/depth	DH	mm
Pattern density	PL	-
Variance parameter	PSE	-

Pattern offset from edge:

Name	Code	Unit
left	OL	mm
right	OR	mm
top	OT	mm
bottom	OB	mm

Pattern adjustment:

Name	Code	Unit
Shift X	TX	mm
Shift Y	TY	mm
Pattern scale	TS	-
Pattern rotation	TR	deg
Remove geometry less than	GE	mm