



Model 2772_25_D




Examples

X=444, Y=158, Z=16, D=6, H=3, OL=0, OR=0, OT=10, OB=10, VA=0, TX=0, TY=0, TS=1, TR=180, GE=0, KU=9, KV=9



VA=1, KD=3, KDS=9, other parameters are the same



X=444, Y=158, Z=16, D=6, H=2, OL=0, OR=0, OT=10, OB=10, VA=2, TX=0, TY=0, TS=1, TR=180, GE=9, KU=9, KV=5, KD=4, KDS=7



Parameters

Main

Name	Code	Unit
Overall dimension X	X	mm
Overall dimension Y	Y	mm
Overall dimension Z	Z	mm
Outline arc width	D	mm
Inner arc width / Pattern depth	H	mm
Number of columns U	KU	-
Number of rows V	KV	-
Number of inner arcs	KD	-
Inner arc step	KDS	mm

Pattern offset from edge:

Name	Code	Unit
left	OL	mm
right	OR	mm
top	OT	mm
bottom	OB	mm

Pattern adjustment:

Name	Code	Unit
Shift X	TX	mm
Shift Y	TY	mm
Pattern scale	TS	-
Pattern rotation	TR	deg
Remove geometry less than	GE	mm

Pattern variant VA:

Name	Code	Unit
Outline arcs	0	-

Inner arcs	1	-
Outline and inner arcs	2	-