



Model 2782_25_D




Examples


X=444, Y=158, Z=16, D=4, H=4, OL=5, OR=5, OT=10, OB=10, TX=0, TY=0, TS=1, TR=0, GE=0, RC=0.5;0.5, R1=288, R2=18, KR=45, KL=10



OL=0, OR=0, R1=70, R2=35, other parameters are the same



OL=0, OR=0, R1=160, R2=35, RC=0.3;0.5, other parameters are the same



KL=15, (OL, OR, OT, OB)=0, R1=340, R2=5, RC=0.5;0.5, other parameters are the same

Parameters

Main

Name	Code	Unit
Overall dimension X	X	mm
Overall dimension Y	Y	mm
Overall dimension Z	Z	mm
Pattern width	D	mm
Pattern depth	H	mm
Number of lines	KL	-
Radius center (X,Y) (0.0 – 1.0) ;RC (0.0 – 1.0)		-
Outer radius	R1	mm
Inner radius	R2	mm
Rotation angle	KR	deg

Pattern offset from edge:

Name	Code	Unit
left	OL	mm
right	OR	mm
top	OT	mm
bottom	OB	mm

Pattern adjustment:

Name	Code	Unit
Shift X	TX	mm
Shift Y	TY	mm
Pattern scale	TS	-
Pattern rotation	TR	deg
Remove geometry less than	GE	mm

