



Model 2785_25_D




Examples

X=444, Y=158, Z=16, D=4, H=4, OL=5, OR=5, OT=10, OB=10, TX=0, TY=0, TS=1, TR=0, GE=0, RC=0.5;0.5, R1=860, PL=81, KS=8



OL=0, OR=0, RC=0.3;0.5, PL=59, KS=5, other parameters are the same



OL=0, OR=0, PL=56, RC=0.5;1.0, KS=10, other parameters are the same



(OL, OR, OT, OB)=0, PL=57, RC=0.5;1.0, KS=10, other parameters are the same

Parameters

Main

Name	Code	Unit
Overall dimension X	X	mm
Overall dimension Y	Y	mm
Overall dimension Z	Z	mm
Pattern width	D	mm
Pattern depth	H	mm
Number of pattern segments	KS	-
Outer radius	R1	mm
Radius center (X,Y) (0.0 – 1.0) ;RC (0.0 – 1.0)		-
Pattern density	PL	-

Pattern offset from edge:

Name	Code	Unit
left	OL	mm
right	OR	mm
top	OT	mm
bottom	OB	mm

Pattern adjustment:

Name	Code	Unit
Shift X	TX	mm
Shift Y	TY	mm
Pattern scale	TS	-
Pattern rotation	TR	deg
Remove geometry less than	GE	mm

