



Model 2786_25_D




Examples

X=444, Y=158, Z=16, D=4, H=4, OL=0, OR=0, OT=0, OB=0, TX=0, TY=0, TS=1, TR=0, GE=0, SXS=120, SYS=10, SL=9



TS=0.95, other parameters are the same



TS=1.2, TR=25, other parameters are the same



TS=1.5, TR=35, other parameters are the same



Parameters

Main

Name	Code	Unit
Overall dimension X	X	mm
Overall dimension Y	Y	mm
Overall dimension Z	Z	mm
Pattern width	D	mm
Pattern depth	H	mm
Pattern start X	SXS	mm
Pattern start Y	SYS	mm
Line step	SL	mm

Pattern offset from edge:

Name	Code	Unit
left	OL	mm
right	OR	mm
top	OT	mm
bottom	OB	mm

Pattern adjustment:

Name	Code	Unit
Shift X	TX	mm
Shift Y	TY	mm
Pattern scale	TS	-
Pattern rotation	TR	deg
Remove geometry less than	GE	mm